EDITORIAL INDEX - 1986

BUILDING REMODELING/RETROFIT

Exterior Insulating Finish System — Jan. ... 20
Window Retrofit Statistics — Jan. ... 28
Replacement Windows — Jan. ... 30
Replacement Windows — Jan. ... 32
Replacement Windows — Jan. ... 34
Replacement Windows — Jan. ... 40
Indirect Lighting Retrofit (case study) — Jan. ... 90
HVAC Retrofit (case study) — Jan. ... 96
Lighting Systems Retrofit — Feb. ... 56
Public Washroom Renovation — Feb. ... 62
Floodlighting Retrofit (case study) — Feb. ... 92
Lighting Retrofit (case study) — Feb. ... 100
Energy Management Systems Retrofit — March ... 87
Competitive Design/Competitive Build — March ... 92
Lighting Retrofit (case study) — March ... 104
Cooling System Retrofit (case study) — March ... 112
Lighting Retrofit (case study) — March ... 116
Building Redesign Blends Old with New — May ... 16
Commercial Carpeting Specification Guidelines — May ... 22
100 Years of Office Space Evolution: A Retrospective — May ... 30
Office Design: Key Acoustical Issues — May ... 36
Office Planning: Access Floor Systems — May ... 42
Access Floor Product Review — May ... 43
Intelligent Building Retrofit — May ... 61
Office Wiring Systems — May ... 66
Security Lighting Retrofit Program — June ... 58
Data-Ready Telephone System (case study) — June ... 82
Polycarbonate Sheet Overglazing for Windows (case study) — June ... 96
Construction Quality Control — July ... 18
Selecting, Evaluating Contractors — July ... 42
Owner Liability Safeguards — July ... 58
Construction Liability: Dispute Resolution — July ... 70
Time, Materials Contracts — July ... 80
Replacement Windows (case study) — July ... 88
Movable Interior Wall System (case study) — July ... 90
Exit Lighting Upgrade — Aug. ... 56
Lighting Retrofit (case study) — Aug. ... 70
Lighting Retrofit (case study) — Aug. ... 72
Remodeling Case Study: Carnegie Hall — Sept. ... 20
Remodeling Case Study: Healey Building — Sept. ... 28
Remodeling Case Study: Phoenix Civic Plaza — Sept. ... 40
Remodeling Case Study: Sears House — Sept. ... 50
Remodeling Case Study: The Tivoli — Sept. ... 58
Remodeling Case Study: Pan Am Building — Sept. ... 67
Remodeling Case Study: Good Samaritan Hospital — Sept. ... 24
Remodeling Case Study: Traders Building — Sept. ... 80
Remodeling Case Study: Signers Hall — Sept. ... 86
Remodeling Case Study: Montgomery Park — Sept. ... 94
1986 Remodeling/Replacement Survey — Sept. ... 104
Open Plan Office Systems — Sept. ... 108
Renovation Pre-Planning: Structural Analysis — Sept. ... 116
The Maintenance Factor in Carpet Specifying — Sept. ... 122
Computerized Project Management — Sept. ... 130
The Single-Ply Alternative — Sept. ... 132
Rubber-Based Single-Ply Membranes — Sept. ... 136
Demountable Wall System (case study) — Sept. ... 153
Exterior Insulative Elastomeric Coating (case study) — Sept. ... 154
Telecommunications Retrofit Planning — Oct. ... 56
Centrifugal Chiller Retrofit (case study) — Oct. ... 75
Carpet Tile Alternative — Nov. ... 18
Carpet Tile Product Review — Nov. ... 24
Energy-Saving Retrofits — Nov. ... 76
Single-Ply Retrofit (case study) — Nov. ... 84
Renovation Includes Wall Insulation (case study) — Nov. ... 86
Boiler Combustion Trim Control Systems — Dec. ... 22
Heat Exchanger Technology Application — Dec. ... 40
Single-Ply Retrofit (case study) — Dec. ... 54
VAV Retrofit (case study) — Dec. ... 50
HVAC Upgrade (case study) — Dec. ... 52

ENERGY MANAGEMENT

HVAC Retrofit (case study) — Jan. ... 96
Shared Energy Savings Concept — March ... 22
Energy-Conscious Design Approach — March ... 30
Optimizing HVAC Efficiency with DDC — March ... 38
Cogeneration Systems — March ... 46
AC Variable Frequency Drives — March ... 54
Boiler Efficiency Checklist — March ... 62
Variable Air Volume — An HVAC Option — March ... 70
Water-Saving Strategies — March ... 76
Electric Power Protection Equipment — March ... 80
Energy Management Systems Retrofit — March ... 87
Weather-Responsive EMS (case study) — March ... 108
Cooling System Retrofit (case study) — March ... 112
Air Handling System (case study) — March ... 114
Centrifugal Chiller Maintenance Checklist — April ... 72
Heat-Reflective Window Film (case study) — April ... 130
Occupancy Sensors (case study) — April ... 140
Interior Lighting (case study) — June ... 86
Spray-Applied Urethane Roof System (case study) — June ... 88
Polycarbonate Sheet Overglazing for Windows (case study) — June ... 96
Building Automation System (case study) — June ... 98
HVAC Life-Cycle Cost Analysis — July ... 48
VAV Diffusers (case study) — July ... 92
Thermostatic Radiator Valves (case study) — July ... 96
Passive Infrared Occupancy Sensors (case study) — Sept. ... 148
Building Automation Systems — Oct. ... 26
Chiller Plant Automation — Oct. ... 36
Automatic Lighting Control Systems — Oct. ... 52
Direct Digital Control Technology — Oct. ... 66
Building Automation System (case study) — Oct. ... 74
Centrifugal Chiller Retrofit (case study) — Oct. ... 75
Five-Phase Energy Management Program (case study) — Oct. ... 80
Saving Energy Dollars with Retrofits — Nov. ... 76
Spray-Applied Insulative Roofing System (case study) — Nov. ... 80
Cooling Towers with Vibration Control (case study) — Nov. ... 82
Wall Insulation Saves Energy (case study) — Nov. ... 86
HVAC System, Maintenance Contract (case study) — Nov. ... 90
Programmable Lighting Control System (case study) — Nov. ... 92
HVAC Service Contracts — Dec. ... 16
Boiler Combustion Trim Control Systems — Dec. ... 22
Gas Cooling — Dec. ... 28
Thermal Storage — Dec. ... 36
Heat Exchanger Technology Application — Dec. ... 40
Boiler Efficiency — Dec. ... 44
HVAC Automation Options — Dec. ... 46
Modular Boilers (case study) — Dec. ... 56
VAV Retrofit (case study) — Dec. ... 50
HVAC Upgrade (case study) — Dec. ... 52

FACILITY MANAGEMENT

Door Hardware — Jan. ... 46
Attracting, Retaining Tenants with Effective Interior Design — Feb. ... 18
Architectural Signage — Feb. ... 44
Indoor Air Quality — Feb. ... 82
Developing a Physical Maintenance Program — April ... 22
Asbestos Removal: Selecting a Contractor — April ... 42
How Maintenance Affects Return on Investment — April ... 54
Maintenance Management Systems — April ... 58
Maximizing Staff Productivity — April ... 74
Selecting a Housekeeping Contractor — April ... 88
Measuring Staff Productivity — April ... 98

EDITORIAL INDEX - 1986

BUILDING REMODELING/RETROFIT

Exterior Insulating Finish System — Jan. ... 20
Window Retrofit Statistics — Jan. ... 28
Replacement Windows — Jan. ... 30
Replacement Windows — Jan. ... 32
Replacement Windows — Jan. ... 34
Replacement Windows — Jan. ... 40
Indirect Lighting Retrofit (case study) — Jan. ... 90
HVAC Retrofit (case study) — Jan. ... 96
Lighting Systems Retrofit — Feb. ... 56
Public Washroom Renovation — Feb. ... 62
Floodlighting Retrofit (case study) — Feb. ... 92
Lighting Retrofit (case study) — Feb. ... 100
Energy Management Systems Retrofit — March ... 87
Competitive Design/Competitive Build — March ... 92
Lighting Retrofit (case study) — March ... 104
Cooling System Retrofit (case study) — March ... 112
Lighting Retrofit (case study) — March ... 116
Building Redesign Blends Old with New — May ... 16
Commercial Carpeting Specification Guidelines — May ... 22
100 Years of Office Space Evolution: A Retrospective — May ... 30
Office Design: Key Acoustical Issues — May ... 36
Office Planning: Access Floor Systems — May ... 42
Access Floor Product Review — May ... 43
Intelligent Building Retrofit — May ... 61
Office Wiring Systems — May ... 66
Security Lighting Retrofit Program — June ... 58
Data-Ready Telephone System (case study) — June ... 82
Polycarbonate Sheet Overglazing for Windows (case study) — June ... 96
Construction Quality Control — July ... 18
Selecting, Evaluating Contractors — July ... 42
Owner Liability Safeguards — July ... 58
Construction Liability: Dispute Resolution — July ... 70
Time, Materials Contracts — July ... 80
Replacement Windows (case study) — July ... 88
Movable Interior Wall System (case study) — July ... 90
Exit Lighting Upgrade — Aug. ... 56
Lighting Retrofit (case study) — Aug. ... 70
Lighting Retrofit (case study) — Aug. ... 72
Remodeling Case Study: Carnegie Hall — Sept. ... 20
Remodeling Case Study: Healey Building — Sept. ... 28
Remodeling Case Study: Phoenix Civic Plaza — Sept. ... 40
Remodeling Case Study: Sears House — Sept. ... 50
Remodeling Case Study: The Tivoli — Sept. ... 58
Remodeling Case Study: Pan Am Building — Sept. ... 67
Remodeling Case Study: Good Samaritan Hospital — Sept. ... 24
Remodeling Case Study: Traders Building — Sept. ... 80
Remodeling Case Study: Signers Hall — Sept. ... 86
Remodeling Case Study: Montgomery Park — Sept. ... 94
1986 Remodeling/Replacement Survey — Sept. ... 104
Open Plan Office Systems — Sept. ... 108
Renovation Pre-Planning: Structural Analysis — Sept. ... 116
The Maintenance Factor in Carpet Specifying — Sept. ... 122
Computerized Project Management — Sept. ... 130
The Single-Ply Alternative — Sept. ... 132
Rubber-Based Single-Ply Membranes — Sept. ... 136
Demountable Wall System (case study) — Sept. ... 153
Exterior Insulative Elastomeric Coating (case study) — Sept. ... 154
Telecommunications Retrofit Planning — Oct. ... 56
Centrifugal Chiller Retrofit (case study) — Oct. ... 75
Carpet Tile Alternative — Nov. ... 18
Carpet Tile Product Review — Nov. ... 24
Energy-Saving Retrofits — Nov. ... 76
Single-Ply Retrofit (case study) — Nov. ... 84
Renovation Includes Wall Insulation (case study) — Nov. ... 86
Boiler Combustion Trim Control Systems — Dec. ... 22
Heat Exchanger Technology Application — Dec. ... 40
Single-Ply Retrofit (case study) — Dec. ... 54
VAV Retrofit (case study) — Dec. ... 50
HVAC Upgrade (case study) — Dec. ... 52

ENERGY MANAGEMENT

HVAC Retrofit (case study) — Jan. ... 96
Shared Energy Savings Concept — March ... 22
Energy-Conscious Design Approach — March ... 30
Optimizing HVAC Efficiency with DDC — March ... 38
Cogeneration Systems — March ... 46
AC Variable Frequency Drives — March ... 54
Boiler Efficiency Checklist — March ... 62
Variable Air Volume — An HVAC Option — March ... 70
Water-Saving Strategies — March ... 76
Electric Power Protection Equipment — March ... 80
Energy Management Systems Retrofit — March ... 87
Weather-Responsive EMS (case study) — March ... 108
Cooling System Retrofit (case study) — March ... 112
Air Handling System (case study) — March ... 114
Centrifugal Chiller Maintenance Checklist — April ... 72
Heat-Reflective Window Film (case study) — April ... 130
Occupancy Sensors (case study) — April ... 140
Interior Lighting (case study) — June ... 86
Spray-Applied Urethane Roof System (case study) — June ... 88
Polycarbonate Sheet Overglazing for Windows (case study) — June ... 96
Building Automation System (case study) — June ... 98
HVAC Life-Cycle Cost Analysis — July ... 48
VAV Diffusers (case study) — July ... 92
Thermostatic Radiator Valves (case study) — July ... 96
Passive Infrared Occupancy Sensors (case study) — Sept. ... 148
Building Automation Systems — Oct. ... 26
Chiller Plant Automation — Oct. ... 36
Automatic Lighting Control Systems — Oct. ... 52
Direct Digital Control Technology — Oct. ... 66
Building Automation System (case study) — Oct. ... 74
Centrifugal Chiller Retrofit (case study) — Oct. ... 75
Five-Phase Energy Management Program (case study) — Oct. ... 80
Saving Energy Dollars with Retrofits — Nov. ... 76
Spray-Applied Insulative Roofing System (case study) — Nov. ... 80
Cooling Towers with Vibration Control (case study) — Nov. ... 82
Wall Insulation Saves Energy (case study) — Nov. ... 86
HVAC System, Maintenance Contract (case study) — Nov. ... 90
Programmable Lighting Control System (case study) — Nov. ... 92
HVAC Service Contracts — Dec. ... 16
Boiler Combustion Trim Control Systems — Dec. ... 22
Gas Cooling — Dec. ... 28
Thermal Storage — Dec. ... 36
Heat Exchanger Technology Application — Dec. ... 40
Boiler Efficiency — Dec. ... 44
HVAC Automation Options — Dec. ... 46
Modular Boilers (case study) — Dec. ... 56
VAV Retrofit (case study) — Dec. ... 50
HVAC Upgrade (case study) — Dec. ... 52

FACILITY MANAGEMENT

Door Hardware — Jan. ... 46
Attracting, Retaining Tenants with Effective Interior Design — Feb. ... 18
Architectural Signage — Feb. ... 44
Indoor Air Quality — Feb. ... 82
Developing a Physical Maintenance Program — April ... 22
Asbestos Removal: Selecting a Contractor — April ... 42
How Maintenance Affects Return on Investment — April ... 54
Maintenance Management Systems — April ... 58
Maximizing Staff Productivity — April ... 74
Selecting a Housekeeping Contractor — April ... 88
Measuring Staff Productivity — April ... 98

Computerized Property Management — April 112
Office Design: Key Acoustical Issues — May 36
Office Planning: Access Floor Systems — May 42
Access Floor Product Review — May 43
Quality Lighting in the Electronic Office — May 50
Intelligent Buildings — May 60
Office Wiring Systems — May 66
Wire Management Using Divided Raceway (case study) — May 84
Impact of Security Planning on Building Economics — June 18
Access Control Systems — June 42
Construction Quality Control — July 18
Addressing Telecommunications, Data Requirements — July 34
Selecting, Evaluating Contractors — July 42
HVAC Life-Cycle Cost Analysis — July 48
Owner Liability Safeguards — July 58
Site Evaluation Process — July 66
Construction Liability: Dispute Resolution — July 70
Time, Materials Contracts — July 80
Movable Interior Wall System (case study) — July 90
Sound-Absorbing Acoustic Foam (case study) — July 98
Open Plan Office Systems — Sept. 108
Renovation Preplanning: Structural Analysis — Sept. 116
Computerized Project Management — Sept. 130
Demountable Wall System — Sept. 153
Intelligent Buildings — Oct. 16
Shared Tenant Services — Oct. 48
Telecommunications Planning — Oct. 56
Property Management System (case study) — Oct. 76
Pre-planning Computerized Facility Management — Nov. 30
Measuring Indoor Air Quality — Nov. 38
Designing a Flexible Office Plan — Nov. 48
Relief From the Relocation Headache — Nov. 68
Computerized Facility Management (case study) — Nov. 84

LIGHTING

Indirect Lighting Retrofit (case study) — Jan. 90
Lighting Systems Retrofit — Feb. 56
Floodlighting Retrofit (case study) — Feb. 96
Lighting Retrofit (case study) — Feb. 100
Roof-Mounted Floodlights (case study) — March 102
Lighting Retrofit/Delamping (case study) — March 104
Lighting Retrofit (case study) — March 116
Occupancy Sensors (case study) — April 140
Quality Lighting in the Electronic Office — May 50
Security Lighting Retrofit Program — June 58
Interior Lighting (case study) — June 86
Cost-Effective Lighting Control Options — Aug. 18
Lighting the Electronic Office — Aug. 28
High Pressure Sodium Security Lighting — Aug. 38
Strategic Lighting Maintenance — Aug. 44
Ambient Lighting in the Open Office — Aug. 52
Exit Lighting Upgrade — Aug. 56
Emergency Lighting Product Review — Aug. 60
Selecting Security Lighting: End-User Guidelines — Aug. 64
Lighting Retrofit (case study) — Aug. 70
Lighting Retrofit (case study) — Aug. 72
Passive Infrared Occupancy Sensors (case study) — Sept. 148
Automatic Lighting Control Systems — Oct. 52
Programmable Lighting Control System (case study) — Nov. 92

LIFE SAFETY/SECURITY

Door Hardware, Exit Devices — Jan. 46
Fire Barrier Floor Penetration Sealant (case study) — Jan. 98
Card Access Systems — Feb. 68
Fire/Smoke Containment — Feb. 76
Roof-Mounted Floodlights (case study) — March 102
Asbestos Removal: Selecting a Contractor — April 42
Asbestos Removal Procedures — April 48
Impact of Security Planning on Building Economics — June 18
Skyway System: Public Area Security — June 26
Fire Safety Foresight — June 34
Fire-Resistant Furnishings — June 38
Access Control Systems — June 42
University Residence Hall Safety/Security (case study) — June 43
Card Access Systems Product Review — June 52
Security Lighting Retrofit Program — June 58
Computer Crime: Safeguarding Information — June 66
Automatic Doors (case study) — June 76
Electronic Security System (case study) — June 84
Access Control, Alarm Monitoring System (case study) — June 90
High Pressure Sodium Security Lighting — Aug. 38
Selecting Security Lighting: End-User Guidelines — Aug. 64
Measuring Indoor Air Quality — Nov. 38
PCB Transformers and Owner Responsibility — Nov. 58

EXTERIOR/INTERIOR MAINTENANCE

Exterior Insulating Finish System — Jan. 20
Infrared Roof Moisture Surveys — Jan. 54
Roof Maintenance Programs — Jan. 60
Standing Seam Metal Roof Systems — Jan. 68
Single-Ply Roofing — Jan. 74
Marble Maintenance — Jan. 86
Elastomeric Roof Coating (case study) — Jan. 92
Solar Reflective Roof System (case study) — Jan. 94
Torch-Applied Roofing System (case study) — Jan. 99
Elevator Efficiency — Feb. 26
Tree Maintenance — Feb. 36
Public Washroom Design/Renovation — Feb. 62
Exterior Restoration (case study) — Feb. 96
Solar-Reflective, 5-Ply Roofing System (case study) — Feb. 102
Non-woven Polyester Roofing Material (case study) — Feb. 104
EPDM Single-Ply Roofing (case study) — March 106
Reroofing Considerations — April 30
Asbestos Removal: Selecting a Contractor — April 42
Asbestos Removal Procedures — April 48
Ultra High Speed Floor Care Technology — April 66
Carpet Maintenance — April 78
Upright Vacuum Product Review — April 82
Floor Scrubbers (case study) — April 120
Indoor Carpeting (case study) — April 124
UV-Resistant Single-Ply Membrane (case study) — April 135
Asbestos-Free Elastomeric Roof Coating (case study) — April 136
Commercial Carpeting Specification Guidelines. — May 22
Spray-Applied Urethane Roof System (case study) — June 88
Single-Ply Roof System (case study) — July 95
Elevating Construction Platforms (case study) — July 100
The Maintenance Factor in Carpet Specifying — Sept. 122
The Single-Ply Alternative — Sept. 132
Rubber-Based Single-Ply Membranes — Sept. 136
Built-Up Roofing: Pre-Construction Evaluation — Sept. 140
Floor Care Equipment (case study) — Sept. 150
Exterior Insulative Elastomeric Coating (case study) — Sept. 154
Single-Ply Roofing System (case study) — Oct. 76
Wood Floor Maintenance — Nov. 26
Spray-Applied Insulative Roofing System (case study) — Nov. 80
Single-Ply Retrofit (case study) — Nov. 84
HVAC System, Maintenance Contract (case study) — Nov. 90
HVAC Service Contracts — Dec. 16
Boiler Efficiency — Dec. 44
Single-Ply Retrofit (case study) — Dec. 54

Copies of articles from this publication are now available from the UMI Article Clearinghouse.

Mail to: University Microfilms International
300 North Zeeb Road, Box 91 Ann Arbor, MI 48106